


Installation instructions Clamp adapter

e**fector 300** E40160 E40174




UK

Functions and features


Installation of probe sensors with a diameter of 10 mm in $R^{1/2}$ (E40160) or $\frac{1}{2}$ "NPT (E40174) process connections.

Installation


Screw the adapter into the process connection and tighten it.




- ► Set the installation length.
- ► Tighten the coupling nut manually.



► Mark its position with lines (A).



Tighten the coupling nut with a tool by 1¼ turn (tightening torque 45 Nm).




Removal:

► Loosen the nut, pull out the sensor.

Repeated installation

- ▶ Insert the sensor again.
- Tighten the nut with a tool without applying too much force until the initial position is reached. For reliable sealing, tighten a bit more.

Scale drawing



- 1: coupling nut
- 2: clamping ring back
- 3: clamping ring front
- 4: fitting